



AC45 MEASUREMENT NOTICE No 2

Fairing of Daggerboard Dry Laminate Areas

A couple of teams have expressed concern about “dry” laminate areas on the bottom of their daggerboards.

They also have noted small voids in the weave of these dry laminate areas.

Approval has been sought to fill these voids and fair these dry areas.

The measurement committee is prepared to inspect these areas and upon confirmation of this problem, grant approval for a limited repair to be undertaken.

This approval will only be granted after inspection and agreement of specific areas for repair.

Any fairing must not change the shape of the board. Upon completion the board will be inspected and checked with templates to ensure the shape is not changed.

The weave pattern shall remain visible upon completion of the repair.

Issued on behalf of the Measurement Committee on July 7, 2015

Ken McAlpine

Chief Measurer 35th America's Cup