



AC45 MEASUREMENT NOTICE No 9

Wing Tip Trolley Mount Modification

ACTV have requested that all wing spars be fitted the trolley mount at the wing tip to simplify access to electronic media equipment in the spar when the spar is on the trolleys.

A drawing of the socket is attached to the email sending this Notice.

This fitting was built into the older spars but not into the newer spars.

Please check your wing spar and fit this socket if it is not installed prior to wing weight and CG measurement in Oman.

Issued on behalf of the Measurement Committee January 5, 2016

Ken McAlpine

Chief Measurer 35th America's Cup